



PARTIAL TOPOGRAPHIC SURVEY

PART OF THE SOUTHEAST QUARTER OF THE SOUTHWEST QUARTER,
AND PART OF THE SOUTHWEST QUARTER OF THE SOUTHEAST
QUARTER, ALL IN SECTION 31, TOWNSHIP 02 NORTH, RANGE 07 EAST,
TOWN OF MONROE, GREEN COUNTY, WISCONSIN.




ASSUMED NORTH



LEGEND	
+ 102.8	SPOT ELEVATION (FEET)
— OH —	OVERHEAD POWER LINE
— SAN —	SEPTIC SYSTEM PIPE
— FO —	BURIED FIBER OPTIC / COMMUNICATION LINE
⊙	UTILITY POLE
⊠	FIBER OPTIC / COMMUNICATION JUNCTION BOX
⊗	DECIDUOUS TREE (TRUNK DIAMETER IN INCHES)
⊗*	CONIFEROUS TREE (TRUNK DIAMETER IN INCHES)
—○—	WOOD RAIL FENCE
—+—	WIRE FENCE

NOTES:

1. Parcel address: 7116 Keller Road, Monroe, WI 53566
2. Dates of field work: February 6 & 7, 2007.
3. Vertical Benchmark: The concrete garage floor at the middle of the double garage door at the main house has an elevation of 100.00 feet (assumed datum).
4. Routing of public utilities is based upon markings provided by Digger's Hotline Ticket Number 20070502031 and above-ground structures visible at the time of survey. Additional buried utilities or structures may be encountered. No excavations were made to locate utilities. Before excavations are performed contact Digger's Hotline.
5. No attempt has been made as a part of this topographic survey to obtain or show data concerning condition or capacity of any utility or municipal/public service facility. For information regarding these utilities or facilities, please contact the appropriate agencies.
6. Septic & water: Bruce Duemler (owner) provided information about septic and water pipes around house and studio: Septic and water to studio follows underground telephone / communication line between house & studio. Note surveyed septic cleanout near southwest corner of house. Septic pipe from house to tank and field exits north side of house, through surveyed cleanouts, and toward west. Pipe location shown is approximate.
7. Building dimensions are to foundation unless noted.
8. All surface and subsurface improvements on and adjacent to the site are not necessarily shown hereon.
9. All trees, hedges and ground cover on the site may not necessarily be shown hereon.
10. Due to snow cover at the time of this survey, only visible improvements above the snow or where the snow was removed were located.
11. Except as specifically stated or shown on this map, this survey does not purport to reflect any of the following which may be applicable to the subject real estate: easements; building setback lines; restrictive covenants; subdivision restrictions; zoning or other land use regulations; and any other facts that an accurate and current title search may disclose.
12. Surveyor has made no investigation or independent search for easements of record, encumbrances, restrictive covenants, ownership title evidence, or any other facts that an accurate and current title search may disclose.



SURVEYED FOR:
Bruce & Tina Duemler
7116 Keller Road
Monroe, WI 53566

SURVEYED BY:

Burse
surveying & engineering
1400 E. Washington Ave, Suite 158
Madison, WI 53703 608.250.9263
Fax: 608.250.9266
email: burse@chonus.net
www.bursesurveyengr.com